

MI 1
II (I+D)
WHb = 4,50
E

MI 2
II
WHb = 5,50
E

MI 3a
II (I+D)
WHb = 4,50
E

MI 3b
II
WHb = 5,50
D

